





PRO2500-EKO 1 SPEED CONTROL PANEL

www.prosisasensor.com

	0	1	2	3	4	5	6	7	8	9
A	10A  FUPS Ups Fuse					6A  F24 Panel 24V Fuse				
	A1-  A2 Down Contactor for 2 speed					1A  F110 Safety Circuit Fuse				
	A1-  A2 Up Contactor for 2 speed									
B	A1-  A2 Fast Speed Contactor for 2 speed					6A  FR R Phase Fuse				
	A1-  A2 Slow Speed Contactor for 2 speed					 Side Contact Normaly Open				
	A1-  A2 Panel Supply Contactor					 Side Contact Normaly Close				
C	A1-  A2 Machine Contactor					 Panel 24V Diode				
	A1-  A2 Rescue Contactor					 Brake Diode				
	A1-  A2 Brake Contactor					 Lirpomp (cam) Diode				
D										
E	 Transformer					 KX Contactor Main Contacts				
F	FSM / 3X25A  4X40A Panel supply fuse					FTR /13-18A  Slow Speed Termal Relay				
						CONTROL PANEL			DRAWING DESCRIPTION	
						Drawing: HEYTECH AB-GE			Page 2H	
						VERS. 1.0				

